

HMP155A

Temperature and Relative Humidity Probe



Table of contents

1. Introduction	1
2. Precautions	1
3. Initial inspection	1
4. QuickStart	2
5. Overview	4
6. Specifications	5
6.1 Temperature sensor	7
6.2 Relative humidity sensor	8
7. Installation	8
7.1 Wiring to data logger	8
7.2 Data logger programming	10
7.2.1 VoltSE() instruction	10
7.2.2 VoltDiff() instruction	11
7.3 Mounting	11
7.3.1 Installation in a 41005-5 14-plate shield	13
7.3.2 Installation in a RAD14 14-plate shield	14
7.3.3 Mount the shield	14
8. Operation	15
8.1 Measurement	15
8.2 Long cable lengths	15
8.3 Absolute humidity	16
9. Troubleshooting and maintenance	17
9.1 Troubleshooting	17
9.2 Maintenance	17
9.2.1 Cleaning	18
9.2.2 Changing the probe filter	18

10. References	19
Appendix A. Importing Short Cut code into CRBasic Editor	21
Appendix B. RS-485 output	22
B.1 SDM-SIO1A or SDM-SIO4A serial I/O module interface option	22
B.2 MD485 interface option	23
B.2.1 MD485 multidrop interface configuration	27
B.3 Numeric display	29

1. Introduction

The HMP155A probe monitors relative humidity (RH) for the range of 0 to 100% RH and temperature for the range of –80 to 60 °C. It provides reliable measurements for a wide range of applications as part of a weather station system or as a single instrument. All Campbell Scientific data loggers are compatible.

NOTE:

This manual provides information only for CRBasic data loggers. For retired Edlog data logger support, see an older manual at www.campbellsci.com/old-manuals .

2. Precautions



- READ AND UNDERSTAND the [Safety](#) section at the back of this manual.
- Care should be taken when opening the shipping package to not damage or cut the cable jacket. If damage to the cable is suspected, contact Campbell Scientific.
- Although the HMP155A is rugged, it should be handled as a precision scientific instrument.
- Do not touch the sensor element.
- Santoprene® rubber, which composes the black outer jacket of the cable, will support combustion in air. It is used because of its resistance to temperature extremes, moisture, and UV degradation. It is rated as slow burning when tested according to U.L. 94 H.B. and passes FMVSS302. However, local fire codes may preclude its use inside buildings.

3. Initial inspection

- Upon receipt of the HMP155A, inspect the packaging and contents for damage. File damage claims with the shipping company.
- The model number and cable length are printed on a label at the connection end of the cable. Check this information against the shipping documents to ensure the expected product and cable length were received.


4. QuickStart

A video that describes data logger programming using *Short Cut* is available at:


www.campbellsci.com/videos/cr1000x-data-logger-getting-started-program-part-3 . *Short Cut* is an easy way to program your data logger to measure the sensor and assign data logger wiring terminals. *Short Cut* is available as a download on www.campbellsci.com . It is included in installations of *LoggerNet*, *RTDAQ*, and *PC400*.

The following procedure also shows using *Short Cut* to program the HMP155A.

1. Open *Short Cut* and click **Create New Program**.
2. Double-click the data logger model.
3. In the **Available Sensors and Devices** box, type HMP155A or locate the sensor in the **Sensors > Meteorological > Relative Humidity & Temperature > HMP155 Temperature and Relative Humidity Sensor** folder. Double-click either **HMP155 (constant power)** or **HMP155 (panel switched power)**; the panel switched power option uses less current but requires a scan rate that is greater than 5 seconds. Data defaults to degree Celsius. This can be changed by clicking the **Deg C** box and selecting **Deg F**, for degrees Fahrenheit, or **K** for Kelvin.




- Click the **Wiring** tab to see how the sensor is to be wired to the data logger. Click **OK** after wiring the sensor.




- Repeat steps three and four for other sensors.
- In **Output Setup**, type the scan rate, meaningful table names, and **Data Output Storage Interval**.

NOTE:
 The HMP155A has a five second settling time after power up; therefore the scan rate must be greater than five seconds when using the panel switched power option.



- Select the measurement and its associated output option.



- Click **Finish** and save the program. Send the program to the data logger if the data logger is connected to the computer.
- If the sensor is connected to the data logger, check the output of the sensor in the data display in *LoggerNet*, *RTDAQ*, or *PC400* to make sure it is making reasonable measurements.

5. Overview

The HMP155A Temperature and Relative Humidity probe contains a platinum resistance temperature detector (PRT) and a Vaisala HUMICAP[®] 180 capacitive relative humidity sensor.

The HMP155A outputs a 0 to 1 VDC signal for temperature and relative humidity that can be measured by all models of Campbell Scientific data loggers with model HMP155ACBL1 cable. The HMP155A also has RS-485 outputs for temperature and relative humidity that can be directly interfaced to the CR6 and CR1000X data logger using the HMP155ACBL2 cable. The RS-485 output can also be used with our CR800, CR850, CR3000, and CR1000 data loggers, but they require both the HMP155ACBL2 cable and the SDM-SIO1A or SDM-SIO4A Serial I/O Module ([RS-485 output](#) (p. 22)). The RS-485 output has a higher current drain than that listed in the specifications.

The HMP155A can be powered continuously, or the power may be switched to conserve battery life. The HMP155A consumes less than 3 milliamps current at 12 VDC. Approximately 2 seconds is required for the sensor to warm up after power is switched on. At measurement rates slower than once per 5 seconds, the overall power consumption (data logger and sensors) may be reduced

by switching power to the HMP155A. Current Campbell Scientific data loggers have a built-in switched 12 VDC that can be used to control power.

NOTE:

HMP155A sensors purchased directly from Vaisala with serial numbers < E4430001 require approximately 5 seconds warm up time.

Features:

- Well-suited for long-term, unattended applications
- Accurate and rugged
- Compatible with the following data loggers: CR6, CR1000X, CR800-series, CR300-series, CR3000, CR1000

6. Specifications

Dimensions in mm [inches]




FIGURE 6-1. Probe dimensions




FIGURE 6-2. Wiring of HMP155A 8-pin connector

*HMP155ACBL1 Cable provided by Campbell Scientific

1 = V_{OUT1} (yellow, temp)

2 = no connection

3 = A_{GND} (white)

4 = V_{OUT2} (blue, RH)

5 = no connection

6 = no connection

7 = V_{CC} (red)

8 = GND (black)

– = SHIELD (clear)

*Note: HMP155ACBL2 for RS-485 is described in [RS-485 output](#) (p. 22).

Operating temperature range for humidity measurement:

–80 to 60 °C (–112 to 140 °F)

Storage temperature range:

–80° to 60 °C (–112 to 140 °F)

Electromagnetic compatibility:

Complies with EMC standard EN61326-1, Electrical equipment for measurement control and laboratory use
- EMC requirements for use in industrial locations

Filter:

Sintered PTFE

Housing material:

PC

Housing classification:


IP66

Weight:	86 g (3 oz)
Voltage outputs:	0 to 1 VDC
Average current consumption:	<3 mA (analog output mode)
Operating voltage:	7 to 28 VDC
Settling time at power-up:	2 s

6.1 Temperature sensor

Measurement range:	-80 to 60 °C (-112 to 140 °F)
Accuracy with voltage output	
at -80 to 20 °C:	$\pm(0.226 - 0.0028 \times \text{temperature}) \text{ } ^\circ\text{C}$
at 20 to 60 °C:	$\pm(0.055 + 0.0057 \times \text{temperature}) \text{ } ^\circ\text{C}$

See the following graph:



Temperature sensor:	Pt 100 RTD 1/3 Class B IEC 751
Response time (63 %) for additional temperature probe in 3 m/s air flow:	63% <20 s 90% <35 s

6.2 Relative humidity sensor

Measurement range:	0 to 100% RH
Accuracy (including non-linearity, hysteresis and repeatability)	
15 to 25 °C (59 to 77 °F):	±1% RH (0 to 90% RH) ±1.7% RH (90 to 100% RH)
-60 to -40 °C (-76 to -40 °F):	± (1.4 + 0.032 × reading) % RH
-40 to -20 °C (-40 to -4 °F):	± (1.2 + 0.012 × reading) % RH
-20 to 40 °C (-4 to 104 °F):	± (1.0 + 0.008 × reading) % RH
40 to 60 °C (104 to 140 °F):	± (1.2 + 0.012 × reading) % RH
Factory calibration uncertainty (20 °C):	±0.6% RH (0 to 40% RH) ±1.0% RH (40 to 97% RH) (Defined as ±2 standard deviation limits. Small variations possible, see also calibration certificate.)
Humidity sensor:	HUMICAP® 180R
Response time for HUMICAP® 180R(C) at 20 °C in still air with sintered PTFE filter and a 0% to 75% RH step change:	20 s (63% step change); 60 s (90% step change)

7. Installation

If you are programming your data logger with *Short Cut*, skip [Wiring to data logger](#) (p. 8) and [Data logger programming](#) (p. 10). *Short Cut* does this work for you. See [QuickStart](#) (p. 2) for a *Short Cut* tutorial.

7.1 Wiring to data logger

The HMP155A probe can be measured with two single-ended or differential analog input channels. Differential measurements are recommended for cable lengths greater than 6.1 m (20 ft). See [Long cable lengths](#) (p. 15).

Connections to CRBasic data loggers are given in [Table 7-1](#) (p. 9) and [Table 7-2](#) (p. 9). To wire an Edlog data logger, see an older manual at www.campbellsci.com/old-manuals, or contact Campbell Scientific for assistance.

Wire color	Wire function	Data logger connection terminal
Yellow	Temperature signal	U configured for single-ended analog input ¹ , SE (single-ended, analog-voltage input)
Blue	Relative humidity signal	U configured for single-ended analog input, SE
White	Signal reference	⊥ (analog ground)
Black	Power ground	⊥
Clear	Shield	⊥
Red	Power	SW12V

¹U terminals are automatically configured by the measurement instruction.

CAUTION:

When measuring the HMP155A with single-ended measurements, the white and black wires must both be connected to ⊥. Doing otherwise will connect the data logger analog and power ground planes to each other, which in some cases can cause offsets on low-level analog measurements. To avoid 3 mA flowing into analog ground, switch the sensor on/off for its own measurement.

Wire color	Wire function	Data logger connection terminal
Yellow	Temperature signal	U configured for differential analog input H ¹ , Diff H
Jumper to White	Temperature signal reference	U configured for differential analog input L, Diff L
Blue	Relative humidity signal	U configured for differential analog input H, Diff H
White	Signal reference	U configured for differential analog input L, Diff L

Table 7-2: Wire color, function, and data logger connection for differential measurements

Wire color	Wire function	Data logger connection terminal
Black	Power ground	G
Clear	Shield	⏏
Red	Power	12V or SW12V


¹U terminals are automatically configured by the measurement instruction.

7.2 Data logger programming

Short Cut is the best source for up-to-date programming code for Campbell Scientific data loggers. If your data acquisition requirements are simple, you can probably create and maintain a data logger program exclusively with **Short Cut**. If your data acquisition needs are more complex, the files that **Short Cut** creates are a great source for programming code to start a new program or add to an existing custom program.

NOTE:

Short Cut cannot edit programs after they are imported and edited in *CRBasic Editor*.

A **Short Cut** tutorial is available in [QuickStart](#) (p. 2). If you wish to import **Short Cut** code into *CRBasic Editor* to create or add to a customized program, follow the procedure in [Importing Short Cut code into CRBasic Editor](#) (p. 21). Programming basics for CRBasic data loggers are provided in the following sections. Downloadable example programs are available at www.campbellsci.com/downloads/hmp155a-example-programs .

Measure the HMP155A with either the **Vo1tSE()** or **Vo1tDiff()** measurement instruction as described in the following sections.

For a discussion on errors caused by long cable lengths, see [Long cable lengths](#) (p. 15).

NOTE:

HMP155A sensors purchased directly from Vaisala with serial numbers < E4430001 require approximately 5 seconds warm up time.

7.2.1 Vo1tSE() instruction

When cable lengths are shorter than 6.1 meters or when power is switched, use the **Vo1tSE()** measurement instruction to measure the temperature and relative humidity. The HMP155A output scale is 0 to 1000 millivolts for the temperature range of –80 to 60 °C and for the relative humidity range of 0 to 100%.

`VoltSE`(Dest, Reps, Range, SEChan, MeasOff, SettlingTime, Integ/FNotch, Mult, Offset)

Variations:

- Temperature reported as °C – set `Mult` to `0.14` and `Offset` to `-80`
- Temperature reported as °F – set `Mult` to `.252` and `Offset` to `-112`
- Humidity reported as a percent – set `Mult` to `0.1` and `Offset` to `0`
- Humidity reported as a fraction – set `Mult` to `0.001` and `Offset` to `0`

7.2.2 `VoltDiff()` instruction

When cable lengths are longer than 6.1 meters or when the sensor is constantly powered, the `VoltDiff()` measurement instruction is used to measure the HMP155A sensor. The HMP155A output scale is 0 to 1000 millivolts for the temperature range of -80 to 60 °C and for the relative humidity range of 0 to 100%.

`VoltDiff`(Dest, Reps, Range, DiffChan, RevDiff, SettlingTime, Integ/FNotch, Mult, Offset)

Variations:

- Temperature reported as °C – set `Mult` to `0.14` and `Offset` to `-80`
- Temperature reported as °F – set `Mult` to `.252` and `Offset` to `-112`
- Humidity reported as a percent – set `Mult` to `0.1` and `Offset` to `0`
- Humidity reported as a fraction – set `Mult` to `0.001` and `Offset` to `0`

7.3 Mounting

Sensors should be located over an open level area at least 9 m (EPA) in diameter. The surface should be covered by short grass or the natural earth surface where grass does not grow. Sensors should be located at a distance of at least four times the height of any nearby obstruction, and at least 30 m (EPA) from large, paved areas. Sensors should be protected from thermal radiation, and adequately ventilated.

Standard measurement heights:

- 1.5 m (AASC)
- 1.25 to 2.0 m (WMO)
- 2.0 m (EPA)

See [References](#) (p. 19) for a list of references that discuss temperature and relative humidity sensors.

Tools required:

- 1/2 inch open-end wrench
- small screwdriver provided with data logger
- UV-resistant cable ties
- small pair of diagonal-cutting pliers
- Adjustable wrench with a minimum 1-7/8 inch jaw size

To install the HMP155A, you will need the 41005-5 or RAD14 14-Plate Radiation Shield. The HMP155A is packaged with a white connector cover and a yellow sensor head protective cap. See [FIGURE 7-1](#) (p. 12).




FIGURE 7-1. HMP155A in shipping box

1. Slide the white connector cover off the sensor head before removing the sensor from the box.

2. Squeeze the sides of the white connector cover and insert the cable's connector through it (see [FIGURE 7-2](#) (p. 13)).



FIGURE 7-2. Cable routed through the connector cover

3. Attach the cable to the mating connector on the bottom of the HMP155A (see [FIGURE 7-3](#) (p. 13)).



FIGURE 7-3. Cable connected to the sensor

4. Slide the white connector cover over the connector and gently push it up as far as it will go. The white connector cover has built-in molded stops that will only allow it to slide up so far (see [FIGURE 7-4](#) (p. 13)).



FIGURE 7-4. HMP155A with connector cover in place and without protective cap

7.3.1 Installation in a 41005-5 14-plate shield

1. Loosely thread the collar adapter into the base of the 14-plate shield.
2. Remove the yellow protective cap on the HMP155A, and insert the sensor into the shield. See [FIGURE 7-5](#) (p. 14) (left) and [FIGURE 7-6](#) (p. 15).
3. Hold the collar and sensor, and finish threading the collar into the shield by hand. Tighten the hex plug so it compresses against the body of the HMP155A to hold it inside the 41005-5 radiation shield. Use an adjustable wrench if necessary, but do not overtighten the collar.

7.3.2 Installation in a RAD14 14-plate shield

1. Loosen the nut on the entry gland at the bottom of the shield.
2. Remove the yellow protective cap on the HMP155A, and insert the sensor into the shield.
3. Insert the sensor up into the gland as far as it will go. See [FIGURE 7-5](#) (p. 14) (right).
4. Using an adjustable wrench, tighten down the nut on the gland until the sensor is held firmly in place. Do not overtighten.

7.3.3 Mount the shield

1. Attach the radiation shield to the tripod mast, crossarm, or tower leg using the supplied U-bolt. See [FIGURE 7-5](#) (p. 14) and [FIGURE 7-6](#) (p. 15) for examples of shield mounting.
2. Route the cable to the data logger, and secure the cable to the mounting structure using cable ties.



FIGURE 7-5. HMP155A and 41005-5 14-plate radiation shield (left) and RAD14 (right) on a tripod mast



FIGURE 7-6. HMP155A and 41005-5 14-plate radiation shield on a CM200-series crossarm

8. Operation

8.1 Measurement

The HMP155A uses a 100 Ω PRT to measure temperature and a Vaisala HUMICAP[®] 180 capacitive sensor to measure relative humidity. Campbell Scientific data loggers measure the analog voltage outputs of the HMP155A Temperature and Relative Humidity Probe with either the [Vo1tSE\(\)](#) or [Vo1tDiff\(\)](#) measurement instruction.

8.2 Long cable lengths

This section describes the error associated with measuring the HMP155A with a single-ended measurement when the probe has a long cable. To avoid these problems, Campbell Scientific recommends measuring the HMP155A using a differential analog measurement when long cable lengths are required. Generic data logger connections for measuring the HMP155A using a differential measurement are given in [Table 7-2](#) (p. 9).

Understanding the details in this section is not required for the general operation of the HMP155A with Campbell Scientific data loggers.

The signal reference (white) and the power ground (black) are connected inside the HMP155A. When the HMP155A temperature and relative humidity are measured using a single-ended analog measurement, both the signal reference and the power ground are connected to ground

at the data logger, and both serve as the return path for 12 V. The voltage will drop along those wires because the wires have resistance.

The HMP155A draws approximately 4 mA when it is powered. The wire used in the HMP155A has resistance of 27.7 Ω /1000 ft. Since the signal reference and the power ground are both connected to ground at the data logger, the effective resistance of those wires together is half of 27.7 Ω /1000 ft, or 13.9 Ω /1000 ft. Using Ohm's law, the voltage drop (V_d), along the signal reference/power ground, is given by Eq. 1 (p. 16).

$$\begin{aligned} V_d &= I \times R \\ &= 4 \text{ mA} \times 13.9 \text{ } \Omega / 1000 \text{ ft} \\ &= 55.6 \text{ mV} / 1000 \text{ ft} \end{aligned} \tag{Eq. 1}$$

This voltage drop will raise the apparent temperature and relative humidity because the difference between the signal and the signal reference wire at the data logger has increased by V_d . The approximate error in temperature and relative humidity is 0.56 $^{\circ}\text{C}$ and 0.56% per 100 feet of cable length, respectively.

8.3 Absolute humidity

The HMP155A measures relative humidity. Relative humidity is defined by the following equation:


$$RH = \frac{e}{e_s} * 100 \tag{Eq. 2}$$

where RH is the relative humidity, e is the vapor pressure in kPa, and e_s is the saturation vapor pressure in kPa. The vapor pressure, e , is an absolute measure of the amount of water vapor in the air and is related to the dewpoint temperature. The saturation vapor pressure is the maximum amount of water vapor that air can hold at a given air temperature. The relationship between dewpoint and vapor pressure, and air temperature and saturation vapor pressure are given by Goff and Gratch (1946), Lowe (1977), and Weiss (1977).

When the air temperature increases, so does the saturation vapor pressure. Conversely, a decrease in air temperature causes a corresponding decrease in saturation vapor pressure. It follows then from Eq. 2 (p. 16) that a change in air temperature will change the relative humidity, without causing a change absolute humidity.

For example, for an air temperature of 20 $^{\circ}\text{C}$ and a vapor pressure of 1.17 kPa, the saturation vapor pressure is 2.34 kPa and the relative humidity is 50%. If the air temperature is increased by 5 $^{\circ}\text{C}$ and no moisture is added or removed from the air, the saturation vapor pressure increases to 3.17 kPa and the relative humidity decreases to 36.9%. After the increase in air temperature,

the air can hold more water vapor. However, the actual amount of water vapor in the air has not changed. Thus, the amount of water vapor in the air, relative to saturation, has decreased.

Because of the inverse relationship between relative humidity and air temperature, finding the mean relative humidity is meaningless. A more useful quantity is the mean vapor pressure. The mean vapor pressure can be computed online by the data logger (see example program available at www.campbellsci.com/downloads/hmp155a-example-programs )

9. Troubleshooting and maintenance

9.1 Troubleshooting

Symptom: Relative Humidity is reported as –9999, NAN, –80 °C, or 0%

1. Check that the sensor is wired to the correct analog input channels as specified by the measurement instructions.
2. Verify the range code for the single-ended or differential measurement instruction is correct for the data logger type.
3. Verify the red power wire is correctly wired to the 12V or SW12V channel. The channel the wire is connected to will depend on the data logger program.

Connect the red wire to a 12V terminal to constantly power the sensor for troubleshooting purposes. With the red wire connected to 12V, a voltmeter can be used to check the output voltage for temperature and relative humidity on the yellow and blue wires respectively (temperature °C = mV * 0.14 – 80.0; relative humidity % = mV * 0.1).

Symptom: Incorrect temperature or relative humidity

1. Verify the multiplier and offset parameters are correct for the desired units ([Data logger programming](#) (p. 10)).

9.2 Maintenance

The HMP155A probe requires minimal maintenance. Check monthly to make sure the radiation shield is free from debris. The white screen at the tip of the probe should also be checked for contaminants.

When installed in close proximity to the ocean or other bodies of salt water, a coating of salt (mostly NaCl) may build up on the radiation shield, sensor, filter and even the chip. NaCl has an affinity for water. The humidity over a saturated NaCl solution is 75%. A buildup of salt on the filter or chip will delay or destroy the response to atmospheric humidity.

The filter can be rinsed gently in distilled water. If necessary, the chip can be removed and rinsed as well. Do not scratch the chip while cleaning.

Recalibrate the HMP155A annually. Refer to the [Assistance](#) page at the back of this document for the procedure for returning the HMP155A to the factory to get recalibrated.

9.2.1 Cleaning

Clean the probe with a soft, lint-free cloth moistened with mild detergent.

9.2.2 Changing the probe filter

1. Remove the filter from the probe.
2. After removing the filter, check the O-ring and change it if necessary.
3. Install a new filter on the probe.

New filters can be ordered from Campbell Scientific or Vaisala.




FIGURE 9-1. Changing the filter

Long term exposure of the HUMICAP® relative humidity sensor to certain chemicals and gases may affect the characteristics of the sensor and shorten its life. Table 9-1 (p. 19) lists the maximum ambient concentrations, of some chemicals, that the HUMICAP® can be exposed to.

Table 9-1: Chemical tolerances of HMP155A	
Chemical	Concentration (PPM)
Organic solvents	1000 to 10,000
Aggressive chemicals (e.g., SO ₂ , H ₂ SO ₄ , H ₂ S, HCl, Cl ₂ , etc.)	1 to 10
Weak acids	100 to 1000
Bases	10,000 to 100,000

10. References

Santoprene® is a registered trademark of Exxon Mobile Corporation.

AASC, 1985: The State Climatologist (1985) Publication of the American Association of State Climatologists: *Heights and Exposure Standards for Sensors on Automated Weather Stations*, v. 9, No. 4 October, 1985. (www.stateclimate.org/publications/state-climatologist/NOAA-NCY-SCBOOKS-SC77097/00000029.pdf)

EPA, 2008: *Quality Assurance Handbook for Air Pollution Measurement Systems*, Vol. IV, Meteorological Measurements, Ver. 2.0, EPA-454/B-08-002 (revised 2008). Office of Air Quality Planning and Standards, Research Triangle Park, NC 27711.

Goff, J. A. and S. Gratch, 1946: Low-pressure properties of water from -160° to 212°F, *Trans. Amer. Soc. Heat. Vent. Eng.*, **51**, 125-164.

Lowe, P. R., 1977: An approximating polynomial for the computation of saturation vapor pressure, *J. Appl. Meteor.*, **16**, 100-103.

Meyer, S. J. and K. G. Hubbard, 1992: Nonfederal Automated Weather Stations and Networks in the United States and Canada: A Preliminary Survey, *Bulletin Am. Meteor. Soc.*, **73**, No. 4, 449-457.

Vaisala, Inc. (2008) HMP155A Humidity and Temperature Probe User Guide, Helsinki, Finland. Text and figures used with permission of Vaisala, Inc.

Weiss, A., 1977: Algorithms for the calculation of moist air properties on a hand calculator, *Amer. Soc. Ag. Eng.*, **20**, 1133-1136.

WMO, 2008. *Guide to Meteorological Instruments and Methods of Observation*. World Meteorological Organization No. 8, 7th edition, Geneva, Switzerland.

Appendix A. Importing *Short Cut* code into *CRBasic Editor*


Short Cut creates a .DEF file that contains wiring information and a program file that can be imported into the *CRBasic Editor*. By default, these files reside in the C:\campbellsci\SCWin folder.

Import *Short Cut* program file and wiring information into *CRBasic Editor*:

1. Create the *Short Cut* program. After saving the *Short Cut* program, click the **Advanced** tab then the **CRBasic Editor** button. A program file with a generic name will open in CRBasic. Provide a meaningful name and save the CRBasic program. This program can now be edited for additional refinement.


NOTE:

Once the file is edited with *CRBasic Editor*, *Short Cut* can no longer be used to edit the program it created.

2. To add the *Short Cut* wiring information into the new CRBasic program, open the .DEF file located in the C:\campbellsci\SCWin folder, and copy the wiring information, which is at the beginning of the .DEF file.
3. Go into the CRBasic program and paste the wiring information into it.
4. In the CRBasic program, highlight the wiring information, right-click, and select **Comment Block**. This adds an apostrophe (') to the beginning of each of the highlighted lines, which instructs the data logger compiler to ignore those lines when compiling. The **Comment Block** feature is demonstrated at about 5:10 in the [CRBasic | Features](#) video .

Appendix B. RS-485 output

The HMP155A outputs a 0 to 1 VDC signal for temperature and relative humidity that can be measured by all models of Campbell Scientific data loggers with model HMP155ACBL1 cable. The HMP155A also has RS-485 outputs for temperature and relative humidity that can be interfaced to the CR6 or CR1000X data loggers with model HMP155ACBL2 cable. The RS-485 output can also be used with our CR800, CR850, CR3000, and CR1000 data loggers, but they require both the HMP155ACBL2 cable and the SDM-SIO1A or SDM-SIO4A Serial I/O Module.

The data logger program that uses the SDM-SIO1A/SIO4A to read the RS-485 output is similar to the program that directly reads the RS-485 output. The data logger program should send the commands 'SMODE RUN' and 'R' to enable the RS-485 output. [SerialInRecord\(\)](#) and [Mid\(\)](#) instructions parse the serial string and put the temperature and relative humidity values into public variables. A downloadable example program is available at www.campbellsci.com/downloads/hmp155a-example-programs.

The MD485 Multidrop Interface can also be used to interface the RS-485 outputs. This option requires a USB to RS-485 cable (available from Vaisala) to change the default baud rate of the RS-485 output from the default of 4800 to a baud rate supported by the MD485.

B.1 SDM-SIO1A or SDM-SIO4A serial I/O module interface option

The SDM-SIO1A/SIO4A module is used to interface the RS-485 outputs of the HMP155A to the data logger. The SDM-SIO1A and SDM-SIO4A have the same functionality. The SDM-SIO4A has more terminals allowing more sensors to be connected to it. The SDM-SIO1A/SIO4A functions like a built-in serial port to the data logger. Data are buffered in the SIO1A/SIO4A and retrieved by the data logger using standard program instructions.

The following table provides wiring to the SDM-SIO1A/SIO4A.

HMP155ACBL2 cable	Vaisala cable ¹	SDM-SIO1A/SIO4A	Data logger	Pin-out
Blue	Pink	RTS/TD+		6
Yellow	Brown	Tx/TD -		2
Black	Red		G	8
Red	Blue		12V	7
White	Green	RG		3
Clear	Black		G	not connected


¹ The gray, pink, and brown wires on the Vaisala cable are not connected.

B.2 MD485 interface option


The MD485 Multidrop Interface can be used to interface the RS-485 outputs of the HMP155A to the data logger **CS I/O** port. Connect the MD485 **CS I/O** port to the data logger **CS I/O** port with an SC12 cable.

The HMP155A has a default RS-485 baud rate of 4800, which must be changed to 9600 to be compatible with the MD485. To change settings in the HMP155A, Vaisala USB to RS-485 cable is required to interface the HMP155A sensor to a computer. Commands to change settings are sent to the HMP155A using a terminal emulator such as Windows *HyperTerminal*.


Vaisala USB to RS-485 cable includes a CD with drivers that must be installed on the computer before the cable can be used. Insert the CD into the computer CD drive and follow the prompts.



Use the **Device Manager** in Windows to determine which COM port the USB/RS-485 cable was assigned:



Configure Windows *HyperTerminal* for the appropriate COM port (for example, COM8 in the example above) for the default HMP155A RS-485 settings of 4800 baud, 7, E, 1.



Using *HyperTerminal*, send the following commands to the HMP155A:


VERS[enter] to get a response from the sensor; for example, HMP155A 1.26

SERI[enter] to get the current RS-485 settings; for example, 4800 E 7 1

SERI 9600 N 8 1[enter] to change the RS-485 settings; response should be 9600 N 8 1

R[enter] to put the sensor in the Run mode to output continuous measurements

The following shows the responses to the commands.




After changing the settings, change the baud rate in *HyperTerminal* to 9600, and make sure the relative humidity and temperature string is being displayed before connecting the sensor to the MD485.

B.2.1 MD485 multidrop interface configuration


Using the *Device Configuration Utility*, configure the MD485 using the following procedure.

1. Open *Device Configuration Utility*.
2. Type MD485 in the **Device Type** box and click MD485.




3. Connect the MD485 to power.
4. Connect the MD485 RS-232 port to a computer serial port.
5. Select the **Communication Port** in the left panel.
6. Click **Connect**.


7. Select CS I/O and RS-485 for the Active Ports and Transparent Communication as the Protocol Configuration.



8. Click the CS I/O tab and select SDC Address 7 for the CS I/O Mode.



9. Click the **RS-485** tab and select **9600** for the **Baud Rate**.



10. Connect the MD485 **CS I/O** port to the data logger **CS I/O** port using an SC12 cable.
11. Use the HMP155ACBL2 to connect the HMP155A sensor to the MD485 and the data logger as shown in the following table. The table also shows wiring for cables purchased from Vaisala.


Table B-2: MD485 to data logger connection

HMP155ACBL2 cable	HMP155A Vaisala cable	MD485	Data logger ¹	Connector pin-out
Blue	Pink	B		6
Yellow	Brown	A		2
Black	Red		G	8
Red	Blue		12V	7
White	Green		G	3
Shield (clear)	Black		G	Not connected

¹ The gray, pink, and brown wires on the Vaisala cable are not used.

B.3 Numeric display

The public variables for temperature and relative humidity can be viewed in the **Numeric Display** mode.



Limited warranty

Products manufactured by Campbell Scientific are warranted by Campbell Scientific to be free from defects in materials and workmanship under normal use and service for twelve months from the date of shipment unless otherwise specified on the corresponding product webpage. See Product Details on the Ordering Information pages at www.campbellsci.com[↗]. Other manufacturer's products, that are resold by Campbell Scientific, are warranted only to the limits extended by the original manufacturer.


Refer to www.campbellsci.com/terms#warranty[↗] for more information.

CAMPBELL SCIENTIFIC EXPRESSLY DISCLAIMS AND EXCLUDES ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. Campbell Scientific hereby disclaims, to the fullest extent allowed by applicable law, any and all warranties and conditions with respect to the Products, whether express, implied or statutory, other than those expressly provided herein.

Assistance

Products may not be returned without prior authorization.

Products shipped to Campbell Scientific require a Returned Materials Authorization (RMA) or Repair Reference number and must be clean and uncontaminated by harmful substances, such as hazardous materials, chemicals, insects, and pests. Please complete the required forms prior to shipping equipment.

Campbell Scientific regional offices handle repairs for customers within their territories. Please see the back page for the Global Sales and Support Network or visit www.campbellsci.com/contact  to determine which Campbell Scientific office serves your country.

To obtain a Returned Materials Authorization or Repair Reference number, contact your CAMPBELL SCIENTIFIC regional office. Please write the issued number clearly on the outside of the shipping container and ship as directed.

For all returns, the customer must provide a "Statement of Product Cleanliness and Decontamination" or "Declaration of Hazardous Material and Decontamination" form and comply with the requirements specified in it. The form is available from your CAMPBELL SCIENTIFIC regional office. Campbell Scientific is unable to process any returns until we receive this statement. If the statement is not received within three days of product receipt or is incomplete, the product will be returned to the customer at the customer's expense. Campbell Scientific reserves the right to refuse service on products that were exposed to contaminants that may cause health or safety concerns for our employees.

Safety

DANGER — MANY HAZARDS ARE ASSOCIATED WITH INSTALLING, USING, MAINTAINING, AND WORKING ON OR AROUND TRIPODS, TOWERS, AND ANY ATTACHMENTS TO TRIPODS AND TOWERS SUCH AS SENSORS, CROSSARMS, ENCLOSURES, ANTENNAS, ETC. FAILURE TO PROPERLY AND COMPLETELY ASSEMBLE, INSTALL, OPERATE, USE, AND MAINTAIN TRIPODS, TOWERS, AND ATTACHMENTS, AND FAILURE TO HEED WARNINGS, INCREASES THE RISK OF DEATH, ACCIDENT, SERIOUS INJURY, PROPERTY DAMAGE, AND PRODUCT FAILURE. TAKE ALL REASONABLE PRECAUTIONS TO AVOID THESE HAZARDS. CHECK WITH YOUR ORGANIZATION'S SAFETY COORDINATOR (OR POLICY) FOR PROCEDURES AND REQUIRED PROTECTIVE EQUIPMENT PRIOR TO PERFORMING ANY WORK.

Use tripods, towers, and attachments to tripods and towers only for purposes for which they are designed. Do not exceed design limits. Be familiar and comply with all instructions provided in product manuals. Manuals are available at www.campbellsci.com. You are responsible for conformance with governing codes and regulations, including safety regulations, and the integrity and location of structures or land to which towers, tripods, and any attachments are attached. Installation sites should be evaluated and approved by a qualified engineer. If questions or concerns arise regarding installation, use, or maintenance of tripods, towers, attachments, or electrical connections, consult with a licensed and qualified engineer or electrician.

General

- Protect from over-voltage.
- Protect electrical equipment from water.
- Protect from electrostatic discharge (ESD).
- Protect from lightning.
- Prior to performing site or installation work, obtain required approvals and permits. Comply with all governing structure-height regulations.
- Use only qualified personnel for installation, use, and maintenance of tripods and towers, and any attachments to tripods and towers. The use of licensed and qualified contractors is highly recommended.
- Read all applicable instructions carefully and understand procedures thoroughly before beginning work.
- Wear a **hardhat** and **eye protection**, and take **other appropriate safety precautions** while working on or around tripods and towers.
- **Do not climb** tripods or towers at any time, and prohibit climbing by other persons. Take reasonable precautions to secure tripod and tower sites from trespassers.
- Use only manufacturer recommended parts, materials, and tools.

Utility and Electrical

- **You can be killed** or sustain serious bodily injury if the tripod, tower, or attachments you are installing, constructing, using, or maintaining, or a tool, stake, or anchor, come in **contact with overhead or underground utility lines**.
- Maintain a distance of at least one-and-one-half times structure height, 6 meters (20 feet), or the distance required by applicable law, **whichever is greater**, between overhead utility lines and the structure (tripod, tower, attachments, or tools).
- Prior to performing site or installation work, inform all utility companies and have all underground utilities marked.
- Comply with all electrical codes. Electrical equipment and related grounding devices should be installed by a licensed and qualified electrician.
- Only use power sources approved for use in the country of installation to power Campbell Scientific devices.

Elevated Work and Weather

- Exercise extreme caution when performing elevated work.
- Use appropriate equipment and safety practices.
- During installation and maintenance, keep tower and tripod sites clear of un-trained or non-essential personnel. Take precautions to prevent elevated tools and objects from dropping.
- Do not perform any work in inclement weather, including wind, rain, snow, lightning, etc.

Maintenance

- Periodically (at least yearly) check for wear and damage, including corrosion, stress cracks, frayed cables, loose cable clamps, cable tightness, etc. and take necessary corrective actions.
- Periodically (at least yearly) check electrical ground connections.

Internal Battery

- Be aware of fire, explosion, and severe-burn hazards.
- Misuse or improper installation of the internal lithium battery can cause severe injury.
- Do not recharge, disassemble, heat above 100 °C (212 °F), solder directly to the cell, incinerate, or expose contents to water. Dispose of spent batteries properly.

WHILE EVERY ATTEMPT IS MADE TO EMBODY THE HIGHEST DEGREE OF SAFETY IN ALL CAMPBELL SCIENTIFIC PRODUCTS, THE CUSTOMER ASSUMES ALL RISK FROM ANY INJURY RESULTING FROM IMPROPER INSTALLATION, USE, OR MAINTENANCE OF TRIPODS, TOWERS, OR ATTACHMENTS TO TRIPODS AND TOWERS SUCH AS SENSORS, CROSSARMS, ENCLOSURES, ANTENNAS, ETC.



Global Sales & Support Network

A worldwide network to help meet your needs



Campbell Scientific Regional Offices

Australia

Location: Garbutt, QLD Australia
Phone: 61.7.4401.7700
Email: info@campbellsci.com.au
Website: www.campbellsci.com.au

Brazil

Location: São Paulo, SP Brazil
Phone: 11.3732.3399
Email: vendas@campbellsci.com.br
Website: www.campbellsci.com.br

Canada

Location: Edmonton, AB Canada
Phone: 780.454.2505
Email: dataloggers@campbellsci.ca
Website: www.campbellsci.ca

China

Location: Beijing, P. R. China
Phone: 86.10.6561.0080
Email: info@campbellsci.com.cn
Website: www.campbellsci.com.cn

Costa Rica

Location: San Pedro, Costa Rica
Phone: 506.2280.1564
Email: info@campbellsci.com
Website: www.campbellsci.com

France

Location: Vincennes, France
Phone: 0033.0.1.56.45.15.20
Email: info@campbellsci.fr
Website: www.campbellsci.fr

Germany

Location: Bremen, Germany
Phone: 49.0.421.460974.0
Email: info@campbellsci.de
Website: www.campbellsci.de

India

Location: New Delhi, DL India
Phone: 91.11.46500481.482
Email: info@campbellsci.in
Website: www.campbellsci.in

South Africa

Location: Stellenbosch, South Africa
Phone: 27.21.8809960
Email: sales@campbellsci.co.za
Website: www.campbellsci.co.za

Spain

Location: Barcelona, Spain
Phone: 34.93.2323938
Email: info@campbellsci.es
Website: www.campbellsci.es

Thailand

Location: Bangkok, Thailand
Phone: 66.2.719.3399
Email: info@campbellsci.asia
Website: www.campbellsci.asia

UK

Location: Shepshed, Loughborough, UK
Phone: 44.0.1509.601141
Email: sales@campbellsci.co.uk
Website: www.campbellsci.co.uk

USA

Location: Logan, UT USA
Phone: 435.227.9120
Email: info@campbellsci.com
Website: www.campbellsci.com